## MANUFACTURING FOR FACE GEARS ABSTRACT OF THE DISCLOSURE

5

Enveloping worm face gears are machined with plunge feeding. Machining could be done by hobbing or cold rolling. This reduces production cost and makes manufacturing easier.